



RENAULT Clio: 1HUG647			
Vinnnumber:	VF15R040H50048052	Versionname:	CLIO IV BER Dynamique
First Registrationdate:	13/03/2014	Fiscalpower:	75PK
Expertise Mileage:	111982	Power Kw:	55
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4314
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/55/16/87 T LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2083,42
Wing R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), LI - Repair and paint (complete)			169,44





Alloy rim R L polished, Damaged, E - Replace 192,96



Trunk lid covering R, Scratch(es), E - Replace 62,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Alloy rim F R polished, Damaged, E - Replace 192,96



Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Damaged, E - Replace 192,96



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Damaged, E - Replace 192,96



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Rear spoiler, Scratch(es), LI - Repair and paint (complete) 115,56



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Burned, Smart repair 64,32



Interior, Stain, Cleaning 150,00



Roof pillar L, Scratch(es), LI - Repair and paint (complete) 176,14

