



OPEL Astra: 1DRJ843

Vinnnumber:	W0LPD8EW9C8111195	Versionname:	ASTRA BRE ecoFLEX Enjoy 150Ys DPF 110PK
First Registrationdate:	1/08/2012	Fiscalpower:	
Expertise Mileage:	151566	Power Kw:	81
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1423
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	337,80
-------------------	---------------

Door F L, Scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Sill outer L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Wing F L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door panel F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display