


OPEL Astra: 1DNR293

Vinnumber:	W0LPD6EW0CG119759	Versionname:	ASTRA BER ecoFLEX Enjoy
First Registrationdate:	2/07/2012	Fiscalpower:	150Ys DPF 110PK
Expertise Mileage:	109468	Power Kw:	81
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3110
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H Steel			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	211,80
Roof pillar R, Bad repair, Acceptable	0,00



Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), E - Replace	0,00



Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Inner door handle F L, Scratch(es), Acceptable	0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------

