



<b>NISSAN Qashqai: 1EVN536</b>			
Vinnnumber:	<b>SJNJCAJ10U7164404</b>	Versionname:	<b>QASHQAI+2 2WD</b>
First Registrationdate:	<b>1/04/2013</b>	Fiscalpower:	<b>Tekna+Nis.Con.DPF 110PK</b>
Expertise Mileage:	<b>57799</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4230</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Panoramic roof	
GPS storage		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		







<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>215/60/17/96 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

<b>Assistance equipment</b>			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>279,83</b>
<b>Door panel R R, Scratch(es), E - Replace</b>			<b>114,00</b>



<b>Rearview mirror housing L, Scratch(es), Acceptable</b>	<b>0,00</b>
---	-------------

<i>No pictures to display</i>		
Ceiling, Stain, P - Check		0,00
		
Trunk lid covering R, Scratch(es), Smart repair		110,64
		
		
Rearview mirror housing R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Damaged, 67 - Polish		55,19
		
Towhook (removable), Not original part, P - Check		0,00
		
Door panel F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Stone chip(s), E - Replace		0,00
		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper cover R M, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		