




RENAULT Scenic: 1EPK038	
Vinnumber:	VF1JZ000D48571016
First Registrationdate:	14/02/2013
Expertise Mileage:	87050
Bodytype:	Hatchback
Gearbox:	MAN 6 VIT
Transmission:	Front
Fueltype:	Diesel
Battery functioning	Yes
Number of doors	5
Number of seats	5
Number head rests	5
Rims summer	Aluminium
Category	Passenger Car
Oil level	OK
Versionname:	SCENIC Energ.Dynamique 130PK
Fiscalpower:	130PK
Power Kw:	96
Body color	Red
Paint type	Metalic
Rims summer	Aluminium
Oil level	OK
Parking lot	2523

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT	3975,56		
Wing R R, Bump(s), LI - Repair and paint (complete)	308,20		



Windscreen, Scratch(es), E - Replace	487,20
--------------------------------------	--------



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Moulding windscreen R, Damaged, E - Replace 100,00



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door trim F R, Scratch(es), E - Replace 114,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Front bumper, Accident, Le - Replace and paint 735,00





Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00




Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Headlight R, Scratch(es), E - Replace 396,00

