



MINI Countryman: 1GSC433

Vinnumber:	WMWZD31030WS17466	Versionname:	MINI COUNTRYMAN Cooper D DPF 112PK
First Registrationdate:	14/04/2014	Fiscalpower:	
Expertise Mileage:	52171	Power Kw:	82
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	205/55/17/95 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			465,00
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00




Roof, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Bad repair, Paint	0,00



Tailgate, Bad repair, Paint 0,00



Rear window, Scratch(es), E - Replace 370,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display