


**RENAULT Scenic: 1FQQ708**

Vinnnumber:	<b>VF1JZ14K649661219</b>	Versionname:	<b>SCENIC Expression 110PK</b>
First Registrationdate:	<b>25/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>126272</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4713</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

215/60/16/96 H Steel				
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>2529,74</b>
-------------------	----------------












Bumper corner R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Gear shift lever cover, Tear, E - Replace	<b>12,00</b>
---	--------------



Roof pillar R, Chemical polution, LI - Repair and paint (complete)	<b>220,18</b>
--	---------------

	Bumper R, Scratch(es), Smart repair	110,64
	Side window trim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Roof pillar L, Scratch(es), LI - Repair and paint (complete)	220,18
	Glove compartment lid, Scratch(es), Smart repair	110,64
	Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
	Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
<i>No pictures to display</i>		
	Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Door R L, Chemical polution, LI - Repair and paint (complete)	318,35
	Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
	Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20



Wheel cover F R, Scratch(es), E - Replace 30,00



Seat cover R R, Tear, E - Replace 360,00



Windscreen, Stone chip(s), Acceptable 0,00

*No pictures to display*

Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Tailgate, Scratch(es), Acceptable 0,00

*No pictures to display*