



## SKODA Octavia: 1GRQ630

Vinnnumber:	<b>TMBJG7NE0E0192363</b>	Versionname:	<b>OCTAVIA COMBI</b>
First Registrationdate:	<b>9/04/2014</b>	Fiscalpower:	<b>GreenLine Ambition 110PK</b>
Expertise Mileage:	<b>121306</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1410</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1415,81</b>
Door R R, Bump(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)			<b>318,35</b>



## Interior, Dirty, Cleaning

100,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Windscreen, Damaged, E - Replace 487,20



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08

