



RENAULT Scenic: 1GKI341			
Vinnnumber:	VF1JZ14K650186524	Versionname:	SCENIC Energy Life 110PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	99172	Power Kw:	81
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3314
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/92 H Steel			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	1804,68
Wing F L, Bump(s), LI - Repair and paint (complete)	220,18



Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 366,35



Door F R, Bump(s), LI - Repair and paint (complete) 318,35



Outer door handle F R, Damaged, E - Replace 54,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door trim R R, Scratch(es), E - Replace 114,00

