



TOYOTA Yaris: 1GHH750			
Vinnnumber:	VNKKD3D330A066059	Versionname:	YARIS BER Hybrid Comfort
First Registrationdate:	7/02/2014	Fiscalpower:	74PK Aut.
Expertise Mileage:	24634	Power Kw:	55
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4806
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		


Options	
Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/65/15/84 H Steel			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes

Total cost ex VAT	500,64
Wing R R, Bad repair, Paint	0,00



Front bumper, Bad repair, Paint	0,00
---------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	---------------



Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Bad repair, Paint	0,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	248,40
---	--------



Door panel trim R R, Damaged, E - Replace	54,00
---	-------



Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Mirror side blinker R, Damaged, E - Replace	28,80



Door R R, Bad repair, Paint	0,00
-----------------------------	------

