



**VOLVO V60: 1HUJ145**

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber:                        | <b>YV1FW8481E1168341</b> | Versionname: | <b>V60 BRE D2 Kinetic 115PK</b> |
| First Registrationdate:            | <b>21/10/2013</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>177538</b>            | Power Kw:    | <b>84</b>                       |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Blue</b>                     |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4322</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

**Options**

|                                |                              |                          |
|--------------------------------|------------------------------|--------------------------|
| Radio CD                       | Central consol F             |                          |
| Windows electric F             | Luggage cover                |                          |
| Windows electric R             | Front parking sensors        |                          |
| Cruise Control                 | Rear parking sensors         |                          |
| Steering wheel multifunctional | Type of Tow bar              | <b>Tow bar removable</b> |
| Radio multimedia               |                              |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                          |
| Type of Lining                 | <b>Lining leather</b>        |                          |
| Type of climate control        | <b>Autom climate control</b> |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/60/16/96 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 7 mm</b> | Re.R. | <b>Bridgestone: 7 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|


|                                      |        |
|--------------------------------------|--------|
| Total cost ex VAT                    | 746,00 |
| Centre console, Burned, Smart repair | 0,00   |



|   |        |
|---|--------|
| Bumper R, Damaged, Le - Replace and paint | 651,00 |
|---|--------|



Rear window, Scratch(es), E - Replace 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*