



|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| <b>SKODA Octavia: 1JLY705</b>      |                          |              |                                 |
| Vinnnumber:                        | <b>TMBJG7NE9F0154616</b> | Versionname: | <b>OCTAVIA COMBI</b>            |
| First Registrationdate:            | <b>20/01/2015</b>        | Fiscalpower: | <b>GreenLine Ambition 110PK</b> |
| Expertise Mileage:                 | <b>156877</b>            | Power Kw:    | <b>81</b>                       |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Grey</b>                |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3330</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Steel</b>             |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

|                                |                              |                  |  |
|--------------------------------|------------------------------|------------------|--|
| <b>Options</b>                 |                              |                  |  |
| GPS storage                    | <b>SD</b>                    | Central consol F |  |
| GPS storage                    |                              | Luggage cover    |  |
| Windows electric F             |                              |                  |  |
| Windows electric R             |                              |                  |  |
| Cruise Control                 |                              |                  |  |
| Steering wheel multifunctional |                              |                  |  |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                  |  |
| Type of GPS                    | <b>GPS big screen color</b>  |                  |  |
| Type of Lining                 | <b>Lining fabrics</b>        |                  |  |
| Type of climate control        | <b>Autom climate control</b> |                  |  |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                             |                |       |                |
|-----------------------|-----------------------------|----------------|-------|----------------|
| <b>Degree of wear</b> |                             |                |       |                |
| Winter tyres:         | <b>195/65/15/91 T Steel</b> |                |       |                |
|                       | Fr.L.                       | Goodyear: 7 mm | Fr.R. | Goodyear: 7 mm |
|                       | Re.L.                       | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

|  |           |            |           |
|--|-----------|------------|-----------|
| <b>Assistance equipment</b>                |           |            |           |
| Repair kit                                 | <b>No</b> | Compressor | <b>No</b> |
| Total cost ex VAT                          |           |            | 275,53    |
| Door R R, Scratch(es), Acceptable          |           |            | 0,00      |
| <i>No pictures to display</i>              |           |            |           |
| Door F R, Scratch(es), Acceptable          |           |            | 0,00      |
| <i>No pictures to display</i>              |           |            |           |
| Engine protective plate, Hole, E - Replace |           |            | 35,00     |

|   |  |  |      |
|---|--|--|------|
| <b>Assistance equipment</b>               |  |  |      |
|   |  |  |      |
| Tailgate, Difference in color, Acceptable |  |  | 0,00 |
| <i>No pictures to display</i>             |  |  |      |
| Door F L, Scratch(es), Acceptable         |  |  | 0,00 |
| <i>No pictures to display</i>             |  |  |      |

no pictures to display

Tyre repair kit, Missing, E - Replace

210,53



Wheel cover R R, Scratch(es), E - Replace

30,00

