



VOLVO V40: 1LBE665

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber: | YV1MV7431G2286948 | Versionname: | 2.0 D2-82 KINETIC |
| First Registrationdate: | 7/08/2015 | Fiscalpower: | |
| Expertise Mileage: | 177763 | Power Kw: | 88 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4409 |
| Maintenance: | 4783KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| GPS storage | | Central consol F |
| GPS storage | HD | Luggage cover |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|---------------------|-------|---------------------|
| | 205/55/16/91 T LightMetal | | | |
| Winter tyres: | Fr.L. | Kleber: 4 mm | Fr.R. | Kleber: 4 mm |
| | Re.L. | Kleber: 4 mm | Re.R. | Kleber: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 405,64 |
|-------------------|--------|

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Wing R L, Bump(s) and scratch(es), It - Spot repair | 115,56 |
|---|--------|



| | |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---|--------|
| Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) | 290,08 |
|---|--------|



| | |
|-------------------------------|------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|--------------------------------|------|
| Wing R L, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

No pictures to display