


**RENAULT Kangoo: 1GGS657**

Vinnumber:	<b>VF1KWX8B550351672</b>	Versionname:	<b>KANGOO Energy Intens 90PK</b>
First Registrationdate:	<b>4/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>50187</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>38952 KM</b>	Parking lot:	<b>1322</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/911 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 7 mm</b>	Fr.R.	<b>Kleber: 7 mm</b>
	Re.L.	<b>Kleber: 7 mm</b>	Re.R.	<b>Kleber: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>95,00</b>
Bonnet, Chemical polution, Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing F R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door R R, Scratch(es), Acceptable			<b>0,00</b>

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

