


BMW 3: 1GBF683

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber: | WBA3K110X0F829597 | Versionname: | 3 TOURING 318d 136PK |
| First Registrationdate: | 13/12/2013 | Fiscalpower: | |
| Expertise Mileage: | 44466 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2727 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | VS | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|----------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | | Luggage cover |
| GPS storage | HD | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining artificial leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/92 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 274,80 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Front bumper, Bump(s), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---|---------------|
| Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|





| | |
|---|-------|
| Door R R, Bad repair, P - Check | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Bump(s), PDR - Knock out without painting | 63,00 |

