



BMW 5: 1GQV614			
Vinnnumber:	WBA5J31090D711138	Versionname:	5 TOURING 520da 163PK Aut.
First Registrationdate:	3/04/2014	Fiscalpower:	
Expertise Mileage:	130833	Power Kw:	120
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2410
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	225/55/17/101 V LightMetal		
	Fr.L.	Fr.R.	
	Michelin: 6 mm	Michelin: 6 mm	
	Re.L.	Re.R.	
	Uniroyal: 6 mm	Uniroyal: 6 mm	

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1703,90
Wing F L, Chemical polution, LI - Repair and paint (complete)			264,21



Sill outer L, Scratch(es), LI - Repair and paint (complete)	372,60
--	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09

