



BMW 5: 1GK173			
Vinnumber:	WBA5C11070D035691	Versionname:	5 BER 518d 136PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	138834	Power Kw:	100
Bodytype:	Berline	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2829
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm


Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			254,16
Wing R L, Scratch(es), Acceptable			0,00



Door R R, Bump(s) and scratch(es), Acceptable	0,00
---	-------------



Roof, Hail damage, PDR - Hail 0,00



Sill outer L, Scratch(es), LI - Repair and paint (complete) 0,00



Wing R R, Bump(s), Acceptable 0,00



Bonnet, Hail damage, PDR - Hail 0,00



Bumper R, Bump(s) and scratch(es), Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

