



BMW 5 TOURING: 1KCC627			
Vinnumber:	<b>WBA5L11020D969239</b>	Versionname:	<b>2.0 518D (110KW) TOURING</b>
First Registrationdate:	<b>30/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>61948</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3723</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
<b>225/55/17/97 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>274,80</b>
Door R R, Bump(s), PDR - Knock out without painting			<b>63,00</b>



Door R L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Front bumper, Bad repair, Paint	<b>0,00</b>



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Stone chip(s), Acceptable 0,00

No pictures to display