



## AUDI A3: 1DUB191

Vinnumber:	<b>WAUZZ8P5DA030594</b>	Versionname:	<b>A3 5B TDie</b>
First Registrationdate:	<b>28/08/2012</b>		<b>Attract.Start/Stop DPF</b>
Expertise Mileage:	<b>65079</b>	Fiscalpower:	<b>105PK</b>
Bodytype:		Power Kw:	<b>77</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>White</b>
Transmission:		Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Battery functioning	<b>Yes</b>	Oil level	<b>OK</b>
Number of doors	<b>5</b>	Parking lot	<b>1630</b>
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>464,80</b>
-------------------	---------------

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------




Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Windscreen, Scratch(es), E - Replace 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 0,00



Roof, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

