



BMW 3: 1GHS463

Vinnumber:	WBA3Y11050D448508	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	11/02/2014	Fiscalpower:	136PK
Expertise Mileage:	124721	Power Kw:	100
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2333
Maintenance:	BINNEN 22000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	2225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	352,92
-------------------	---------------

Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	-------------



Gear shift lever knob, Worn, Acceptable	0,00
---	-------------



Front bumper, Scratch(es), It - Spot repair 115,56



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Bumper corner R L, Scratch(es), It - Spot repair 115,56



Seat cover F L, Worn, P - Check 0,00



Windscreen, Stone chip(s), Windscreen repair 58,80



Wing R R, Bump(s), Acceptable 0,00



Ignition key, Not functioning (well), P - Check 0,00



Door F R, Bump(s), Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

