



AUDI A3: 1CVZ890			
Vinnnumber:	WAUZZZ8P9CA123620	Versionname:	SPORTBACK
First Registrationdate:	9/03/2012	Fiscalpower:	
Expertise Mileage:	88974	Power Kw:	0
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		


Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes

Total cost ex VAT	2011,73
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Chemical polution, LI - Repair and paint (complete)	318,35




Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------

