



CITROEN C5: 1FLS524

Vinnnumber:	VF7RW9HD8DL513529	Versionname:	C5 TOURER e-HDi Bus.GPS BMP 113PK Aut.
First Registrationdate:	9/08/2013	Fiscalpower:	
Expertise Mileage:	92609	Power Kw:	84
Bodytype:	Break	Body color:	Beige
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1632
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/98 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1124,42

Rear window, Scratch(es), E - Replace 370,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy Rims (all), Rust, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Damaged, Smart repair 110,64



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00



Bonnet, Bad repair, Paint 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

