



CITROEN C4 Picasso: 1GAQ196

Vinnumber:	VF73A9HC8DJ811065	Versionname:	GR.C4 PICASSO Seduction
First Registrationdate:	9/12/2013	Fiscalpower:	ETG 115PK Aut.
Expertise Mileage:	71629	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE IN 15400KM	Parking lot:	2721
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 T Steel			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	613,20
Bumper trim R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar L, Bump(s), PDR - Knock out without painting	82,80



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R L, Bump(s), PDR - Knock out without painting 82,80



Wheel cover R R, Damaged, E - Replace 30,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Worn, Acceptable 0,00




Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Roof, Bump(s), PDR - Knock out without painting 82,80



Wheel cover F L, Broken, E - Replace 30,00



Rocker panel inner R L, Bump(s), Acceptable 0,00

No pictures to display

Roof, Chemical polution, P - Check 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80





Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door frame R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display