



FORD KUGA: 1EVQ951

Vinnumber:	WF0AXXWPMAGS38307	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	16621	Power Kw:	88
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4501
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/50/18/101 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1835,49
-------------------	----------------

Interior, Dirty, Cleaning	50,00
---------------------------	--------------



Wing R R, Scratch(es), It - Spot repair	115,56
---	---------------





Tailgate, Scratch(es), LI - Repair and paint (complete)	362,02
---	---------------



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 577,80



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 348,09



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper corner R L, Scratch(es), Acceptable 0,00

