



BMW X5: 1GEN323

Vinnumber:	WBAKS410600C37780	Versionname:	X5 3.0dA xDrive30 258PK Aut.
First Registrationdate:	16/01/2014	Fiscalpower:	
Expertise Mileage:	51226	Power Kw:	190
Bodytype:	SUV	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3707
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear
























	255/55/18/109 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		3872,52
Door R R, Scratch(es), LI - Repair and paint (complete)		382,02



Wing R R, Chemical polution, LI - Repair and paint (complete)	369,84
--	---------------

			Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84
			Door panel R L, Damaged, E - Replace	132,00
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	362,02
			Ignition key, Damaged, E - Replace	150,00
<i>No pictures to display</i>				
			Rearview mirror housing L, Scratch(es), Smart repair	110,64
			Front bumper, Damaged, Le - Replace and paint	862,80
			Wing F R, Bad repair, Paint	0,00
			Bumper R, Damaged, Le - Replace and paint	766,80
			Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56



Foglight L, Damaged, E - Replace

156,00

