



CITRO?N C-ZERO: 1EJR715

Vinnnumber:	VF71NZKZZDU900220	Versionname:	C-ZERO Electr.Attraction 64PK Aut.
First Registrationdate:	2/01/2013	Fiscalpower:	
Expertise Mileage:	47238	Power Kw:	47
Bodytype:	Hatchback	Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Electric	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2631
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

- Radio CD
- Windows electric F
- Windows electric R
- Type of headlighting **Headlighting Halogen**
- Type of Lining **Lining fabrics**

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	145/65/15/72 T Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

- Number of charging cables (normal) **1**
- Number of charging cables (rapid charge) **1**

Total cost ex VAT	1003,32
Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Radio, Not functioning (well), P - Check	0,00









Sill outer L, Bad repair, Paint	0,00
--	-------------



Internal Boot Lining L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	246,56
	
Wheel cover R R, Scratch(es), E - Replace	24,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
	
Dashboard, Scratch(es), Smart repair	110,64
	
Wheel cover F L, Scratch(es), E - Replace	24,00
	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Ignition key, Damaged, E - Replace	150,00
No pictures to display	
Internal Boot Lining R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover F R, Scratch(es), E - Replace	24,00
	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), LI - Repair and paint (complete)	254,68
