



**LAND ROVER Evoque: 1EUJ481**

Vinnnumber:	<b>SALVB1DC8DH775625</b>	Versionname:	<b>EVOQUE COUPE eD4 2WD</b>
First Registrationdate:	<b>22/03/2013</b>	Fiscalpower:	<b>Pure 150PK</b>
Expertise Mileage:	<b>149909</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3710</b>
Number of doors:	<b>3</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

GPS storage	<b>HD</b>	Seats electric F L	
GPS storage		Seats electric F R	
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunction		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/65/17/102 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Firestone: 4 mm</b>	Fr.R.	<b>Firestone: 4 mm</b>
	Re.L.	<b>Firestone: 4 mm</b>	Re.R.	<b>Firestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>95,00</b>
-------------------	--------------

Wing R L, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------



Door F L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Centre console, Scratch(es), Acceptable 0,00



Backrest cover F L, Worn, Acceptable 0,00



Backrest cover F R, Scratch(es), Acceptable 0,00



Bumper F L, Scratch(es), Acceptable 0,00

