


**BMW 5: 1ERR430**

Vinnnumber:	<b>WBAMX11040DY14532</b>	Versionname:	<b>5 TOURING 520dAS St/St</b>
First Registrationdate:	<b>4/03/2013</b>	Fiscalpower:	<b>163PK Aut.</b>
Expertise Mileage:	<b>151193</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1106</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>285,00</b>
Tailgate, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>





Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror R complete, Damaged, Le - Replace and paint 0,00



Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bump(s), LI - Repair and paint (complete) 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Sill outer R, Scratch(es), LI - Repair and paint (complete) 0,00

