



CITROEN Berlingo: PW9013

Vinnnumber:	VF77B9HF0CN525387	Versionname:	BERLINGO B/F Kort Pro 90PK
First Registrationdate:	25/07/2012	Fiscalpower:	
Expertise Mileage:	184990	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2305
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	802,55
Wheel cover R R, Scratch(es), E - Replace	22,50



Trunk door R L, Bump(s), Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Wing F R, Bump(s), LI - Repair and paint (complete)	165,13
---	---------------















Sliding door R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Front bumper, Stone chip(s), Acceptable	0,00
---	-------------

<i>No pictures to display</i>		
Bumper R, Bump(s), Smart repair		110,64
		
Door F R, Bump(s), PDR - Knock out without painting		63,00
		
Wheel cover F R, Scratch(es), E - Replace		22,50
		
Wing R R, Scratch(es), LI - Repair and paint (complete)		231,15
		
Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)		165,13
		
		
		
Roof, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Roof, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover F L, Scratch(es), E - Replace		22,50
