


**MINI Roadster: 1FXC366**

Vinnnumber:	<b>WMWSY31050T501849</b>	Versionname:	<b>MINI ROADSTER Cooper S 163PK</b>
First Registrationdate:	<b>25/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>95363</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Cabriolet</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2128</b>
Number of doors:	<b>2</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunction	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


**Degree of wear**

	<b>205/45/17/88 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 655,64

**Alloy rim F R, Scratch(es), LI - Repair and paint (complete)** 95,00

**Bonnet, Hail damage, PDR - Hail**
**0,00**



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Hail damage, PDR - Hail 0,00



Wing R L 3P, Bad repair, Paint 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

*No pictures to display*

Ignition key, Missing, E - Replace 150,00

*No pictures to display*

Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Aerial, Damaged, E - Replace 15,00




Wing trim R R, Scratch(es), Smart repair 110,64



Wing R R 3P, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	