



MERCEDES A: 1GKT001

Vinnumber:	WDD1760111J253323	Versionname:	A 160 CDI 90PK
First Registrationdate:	5/03/2014	Fiscalpower:	
Expertise Mileage:	62549	Power Kw:	66
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE A IN 347D	Parking lot:	2326
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Yokohama: 6 mm	Fr.R.	Yokohama: 6 mm
	Re.L.	Yokohama: 7 mm	Re.R.	Yokohama: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			640,00
Alloy rim F R, Scratch(es), I - Repair			50,00



Alloy rim R R, Scratch(es), I - Repair 50,00



Front bumper, Scratch(es), LI - Repair and paint (partial) 220,00



Sill trim L, Scratch(es), LI - Repair and paint (partial) 220,00



Interior, No damage, Acceptable 0,00



Alloy rim R L, Scratch(es), I - Repair 50,00



Bumper R, Bump(s), Acceptable 0,00



Engine protective plate, Tear, Acceptable 0,00



Alloy rim F L, Scratch(es), I - Repair 50,00



Wing R L, Bump(s), Acceptable 0,00

