



MINI Mini: 1GDH703			
Vinnnumber:	WMWSW31090T234771	Versionname:	MINI Cooper D 112PK DPF
First Registrationdate:	7/01/2014	Fiscalpower:	
Expertise Mileage:	78383	Power Kw:	82
Bodytype:		Body color:	Green
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2115
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/55/16/87 V LightMetal			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment	
Jack	Yes
Total cost ex VAT	436,76
Bumper R, Scratch(es), Smart repair	110,64



Wing F L, Scratch(es), It - Spot repair	115,56
---	--------



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), It - Spot repair 115,56



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display