



OPEL Zafira: 1EBQ324

Vinnumber:	W0LPD9EM1D2014453	Versionname:	ZAFIRA TOURER
First Registrationdate:	12/10/2012	Fiscalpower:	ecoFL.Enjoy St/St.130PK
Expertise Mileage:	100640	Power Kw:	96
Bodytype:	MPV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2607
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 H Steel			
Winter tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2738,10

Windscreen, Stone chip(s), Windscreen repair 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F L, Scratch(es), E - Replace 30,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Steel rim R L, Deformed, E - Replace

88,80



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Wheel cover R L, Scratch(es), E - Replace

30,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

0,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)

204,00

raigate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,88



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Interior, Dirty, Cleaning 25,00



Wheel cover F R, Scratch(es), E - Replace 30,00




Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Roof pillar R, Bump(s) and scratch(es), LI - Repair and paint (complete)

220,18



Rear window, Scratch(es), E - Replace

0,00

