



**PEUGEOT Expert: 1EIG437**

Vinnumber:	<b>VF3XS9HM0CZ039470</b>	Versionname:	<b>EXPERT B/F SWB 227 L1H1 90PK</b>
First Registrationdate:	<b>12/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>142460</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1208</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Rear parking sensors	
Windows electric F			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/65/16/104 T Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	1053,09
-------------------	---------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Interior, Dirty, Cleaning	50,00
---------------------------	-------



Internal Boot Lining L, Damaged, Smart repair	110,64
---	--------



Bumper R, Bump(s) and scratch(es), Smart repair 110,64



Internal Boot Lining R, Damaged, Smart repair 110,64



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Smart repair 110,64



Wing F R, Scratch(es), LI - Repair and paint (complete) 165,13



Windscreen, Damaged, E - Replace 395,40

