



MERCEDES CLA: 1GCV472

Vinnnumber:	WDD1173011N058170	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	85274	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE A1 BINNEN 232 DAGEN	Parking lot:	2502
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 V LightMetal			
Winter tyres:	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	BF Goodrich: 4 mm	Re.R.	BF Goodrich: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	115,56
Bumper F R, Scratch(es), It - Spot repair	115,56



Door F R, Bump(s), Acceptable	0,00
-------------------------------	-------------



Wing R L, Bump(s), Acceptable 0,00



Door panel R L, Damaged, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Compressor, Missing, P - Check 0,00

No pictures to display

Wing R L, Bump(s), Acceptable 0,00



Backrest cover F L, Worn, Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00



Door R R, Repaired, P - Check 0,00



Door F L, Bump(s), Acceptable 0,00

