



| | | | |
|---------------------------|--------------------------|--------------|-----------------------------------|
| VOLVO V60: 1ETT309 | | | |
| Vinnumber: | YV1FW84A1D1131730 | Versionname: | V60 D2 Kinetic St/St 115PK |
| First Registrationdate: | 19/03/2013 | Fiscalpower: | |
| Expertise Mileage: | 144377 | Power Kw: | 84 |
| Bodytype: | Break | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3201 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | |
|--------------------------------|--|
| Options | |
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Type of Tow bar Tow bar removable |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| Degree of wear | | | | |
| | 225/45/17/97 V LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

| | | | |
|--|------------|------------|---------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 672,60 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



| | |
|---|---------------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 270,80 |
|---|---------------|



| | |
|--|--------------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



| | |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---------------------------------------|------|
| Sill outer L, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|-------------------------------|------|
| Wing R L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display