



**RENAULT Master 35 L3H1: 1FFV555**

Vinnnumber:	<b>VF1MAF4FE49125759</b>	Versionname:	<b>MASTER 35 B/F L3H2 Gr.Conf.(E5)150PK</b>
First Registrationdate:	<b>18/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>162318</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV29</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/65/16/112 R Steel</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Pirelli: 8 mm</b>	Re.R.	<b>Pirelli: 8 mm</b>

**Assistance equipment**

Total cost ex VAT	1390,41
Sill outer R, Bump(s), LI - Repair and paint (complete)	232,88



Door F L, Scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Floor covering F R, Damaged, E - Replace	237,00
--	--------



Wheel cover R R, Scratch(es), E - Replace 22,50



Wheel cover F R, Scratch(es), E - Replace 22,50



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), LI - Repair and paint (complete) 238,76



Wing F L, Scratch(es), LI - Repair and paint (complete) 165,13



Sill outer L, Scratch(es), LI - Repair and paint (complete) 232,88



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display