



PEUGEOT 208: 1ELB244

Vinnumber:	VF3CC8HR0CT157622	Versionname:	208 BER Active 68PK
First Registrationdate:	10/01/2013	Fiscalpower:	
Expertise Mileage:	61770	Power Kw:	50
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	-100KM	Parking lot	3202
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	618,94
-------------------	---------------

Wheel cover F L, Scratch(es), E - Replace	24,00
---	--------------



Wheel cover R R, Missing, E - Replace	24,00
---------------------------------------	--------------



Bonnet, Bump(s), PDR - Knock out without painting 82,80



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Bumper grille, Broken, E - Replace 89,00



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 176,14



Wheel cover F L, Damaged, E - Replace 24,00




Bumper F M, Strained , P - Check 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 25,00



Roof, Bump(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover R L, Scratch(es), E - Replace	24,00
---	-------

