


**TOYOTA YARIS: 1KXZ903 NO EXPERTISE**

Vinnumber:	<b>VNKKD3D380A186231</b>	Versionname:	<b>1.5 VVT-I HYBRID COMFORT AUTO</b>
First Registrationdate:	<b>29/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>92971</b>	Power Kw:	<b>74</b>
Bodytype:		Body color	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level	<b>OK</b>
Maintenance	<b>DERNIERE A 70.817 KM</b>	Parking lot	<b>2212</b>
Maintenance	<b>OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
GPS storage	
GPS storage	<b>HD</b>
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>175/65/15/84 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	194,44
-------------------	--------

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Bumper R, Repaired, P - Check	0,00
-------------------------------	------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)

169,44



Tailgate, Not original part, Remove lettering

25,00

