



AUDI S5: YZ6253

Vinnnumber:	WAUZZZ8T4DA061090	Versionname:	S5 SB Quattro S-tr.333PK
First Registrationdate:	1/03/2016	Fiscalpower:	Aut.
Expertise Mileage:	149349	Power Kw:	245
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1515
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	DVD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/40/18/97 V LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2303,86
-------------------	---------

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
---------------------------------------------------------	--------




Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---------------------------------------------------------	--------



Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Door F R, Chemical polution, LI - Repair and paint (complete) 382,02



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56




Interior, Dirty, Acceptable 0,00



Rear floor , Rust, P - Check 0,00



Tailgate, Chemical polution, LI - Repair and paint (complete) 362,02



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09

