


**BMW 1 HATCH: 1JUJ170**

Vinnumber:	<b>WBA1C91040P991772</b>	Versionname:	<b>1.6 116D EFFICIENTDYNAMICS EDIT. (85KW)</b>
First Registrationdate:	<b>2/03/2015</b>	Fiscalpower:	<b>85</b>
Expertise Mileage:	<b>169301</b>	Power Kw:	<b>White</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>Opaque</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Aluminium</b>
Transmission:	<b>Back</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1113</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b> Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	274,80
-------------------	--------


Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rear spoiler, Hail damage, LI - Repair and paint (complete) 0,00



Bonnet, Hail damage, PDR - Hail 0,00



Roof, Hail damage, PDR - Hail 0,00



Seat cover F L, Stain, Acceptable 0,00



Door R L, Bump(s), PDR - Knock out without painting 63,00



Armrest F Mid, Scratch(es), Acceptable 0,00

