


RENAULT Grand Scenic: 1EOZ684

Vinnnumber:	VF1JZ14B648651076	Versionname:	GR.SCENIC Energ.Dynamique 7pl.FAP 110PK
First Registrationdate:	12/02/2013	Fiscalpower:	81
Expertise Mileage:	161319	Power Kw:	81
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1118
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1398,13
Bumper F M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Window R R door, Scratch(es), E - Replace	0,00





Window F L door, Scratch(es), E - Replace 0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Window R L door, Scratch(es), E - Replace 0,00



Seat cover F L, Worn, Acceptable 0,00



Glove compartment lid, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), E - Replace 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08

