



VOLKSWAGEN GOLF: 1GRE900

| | | | |
|------------------------------------|--------------------------|--------------|------------------------|
| Vinnumber: | WVWZZZAUZEW355285 | Versionname: | Trendline 105PK |
| First Registrationdate: | 7/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 79924 | Power Kw: | 77 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2728 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | SD | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 T Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 385,49 |
|-------------------|---------------|

| | |
|-------------------------------------|-------------|
| Door R R, Stone chip(s), Acceptable | 0,00 |
|-------------------------------------|-------------|

No pictures to display

| | |
|--------------------------------------|-------------|
| Rear window, Scratch(es), Acceptable | 0,00 |
|--------------------------------------|-------------|

No pictures to display

| | |
|----------------------------------|---------------|
| Boot cover, Missing, E - Replace | 137,33 |
|----------------------------------|---------------|



| | |
|---|-------------|
| Internal Boot Lining R, Scratch(es), Acceptable | 0,00 |
|---|-------------|

No pictures to display

| | |
|--|--------|
| Wing R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover F L, Scratch(es), E - Replace | 30,00 |
|  | |
| Wing R L, Bump(s), PDR - Knock out without painting | 102,60 |
|  | |
| Door panel R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover F L, Dirty, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door panel R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover R, Dirty, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Internal Boot Lining L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover F R, Dirty, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 115,56 |
|  | |
| Windscreen, Repaired, P - Check | 0,00 |
|  | |
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rocker panel inner R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Trunk lid covering R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |