



**BMW 1: 1GAD684**

Vinnnumber:	<b>WBA1C91090J519425</b>	Versionname:	<b>1 HATCH 116d Eff.Dyn.Ed. 116PK</b>
First Registrationdate:	<b>4/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>76836</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>BLAUW</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>Blue</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Maintenance	<b>OVER 25000KM</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>2101</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>646,67</b>
-------------------	---------------

Seat cover F L, Worn, P - Check	<b>0,00</b>
---------------------------------	-------------



Bonnet, Hail damage, Forfeit hail (heavy)	<b>0,00</b>
---	-------------



Door F L, Bump(s), PDR - Knock out without painting 63,00



Roof, Hail damage, Forfeit hail (heavy) 0,00



Door R L, Bump(s), PDR - Knock out without painting 63,00



Covering interior front pillar L, Burned, Smart repair 64,32



Foglight L, Damaged, E - Replace 138,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

