



VOLKSWAGEN Polo: 1HLF944

Vinnnumber:	WVWZZZ6RZEY237952	Versionname:	POLO Comfortline DPF 75PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	54419	Power Kw:	55
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2826
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	481,33
-------------------	---------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Boot carpet, Stain, Cleaning	25,00
------------------------------	--------------



Spoiler R, Scratch(es), 67 - Polish	50,00
-------------------------------------	--------------



Roof pillar L, Scratch(es), LI - Repair and paint (complete) 176,14



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), 67 - Polish 55,19



Seat cover R, Stain, Cleaning 25,00

