



**VOLKSWAGEN Passat: 1GQI714**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber:                        | <b>WVWZZZ3CZEE101405</b> | Versionname: | <b>PASSAT VAR Comfortline</b> |
| First Registrationdate:            | <b>1/04/2014</b>         | Fiscalpower: | <b>136PK</b>                  |
| Expertise Mileage:                 | <b>171293</b>            | Power Kw:    | <b>100</b>                    |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Brown</b>             |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3633</b>                   |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting:          | <b>Headlighting Halogen</b>  |
| Type of GPS:                   | <b>GPS big screen color</b>  |
| Type of Lining:                | <b>Lining leather</b>        |
| Type of climate control:       | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>215/55/16/97 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 6 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>1252,21</b> |
|-------------------|----------------|

|                               |             |
|-------------------------------|-------------|
| Wing R R, Bump(s), Acceptable | <b>0,00</b> |
|-------------------------------|-------------|

*No pictures to display*


|   |               |
|---|---------------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b> |
|---|---------------|



|   |               |
|---|---------------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | <b>318,35</b> |
|---|---------------|



|   |        |
|---|--------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|---|--------|



|                                |      |
|--------------------------------|------|
| Wing R R, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

*No pictures to display*

|                             |      |
|-----------------------------|------|
| Wing R L, Bad repair, Paint | 0,00 |
|-----------------------------|------|



|   |        |
|---|--------|
| Wing F R, Scratch(es), LI - Repair and paint (complete) | 220,18 |
|---|--------|



|   |        |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

