


RENAULT Grand Scenic: 1GSD291

Vinnnumber:	VF1JZNAB650711442	Versionname:	GRAND SCENIC Energy R-Movie 7pl.130PK
First Registrationdate:	14/04/2014	Fiscalpower:	
Expertise Mileage:	100059	Power Kw:	96
Bodytype:	MPV	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2505
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
TV/DVD screen R	Panoramic roof
GPS storage	SD
GPS storage	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/5/17/95 V LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	874,60
-------------------	--------

Roof, Stain, Acceptable	0,00
-------------------------	------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Ceiling, Dirty, Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), PDR - Knock out without painting 63,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bumper grille, Broken, E - Replace 59,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door moulding Lower F R, Scratch(es), E - Replace 114,00

