



PEUGEOT Boxer 330: 1EHS686

Vinnnumber:	VF3YASMFA12329756	Versionname:	BOXER 330 B/F SWB HR L1H2 FAP 110PK
First Registrationdate:	6/12/2012	Fiscalpower:	
Expertise Mileage:	79750	Power Kw:	81
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV11
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Rear parking sensors
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/15/105 R Steel			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment


Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	5162,72
-------------------	---------

Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Bonnet, Hail damage, PDR - Hail	375,00
---------------------------------	--------



Rearview mirror housing R, Hole, E - Replace	124,00
--	--------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 327,15




Wing R R, Bump(s), LI - Repair and paint (complete) 231,15



Bumper corner R R, Damaged, E - Replace 680,00



Roof, Hail damage, PDR - Hail 2500,00



Windscreen, Damaged, E - Replace 395,40



Tailgate, Bump(s), LI - Repair and paint (complete) 530,02

