



VOLKSWAGEN Golf: XN9056

Vinnnumber:	WVWZZZAUZEW331536	Versionname:	GOLF BER Highline 105PK
First Registrationdate:	27/03/2014	Fiscalpower:	
Expertise Mileage:	88856	Power Kw:	77
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2601
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	591,80
-------------------	--------

Alloy rim R R polished, Rust, LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R polished, Rust, LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L polished, Rust, LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Rust, LI - Repair and paint (complete) 95,00

