



VOLKSWAGEN CC: 1EGT751

Vinnumber:	WVWZZZ3CZDE541812	Versionname:	CC BMT 136PK
First Registrationdate:	28/11/2012	Fiscalpower:	
Expertise Mileage:	52052	Power Kw:	100
Bodytype:	Berline	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2509
Number of doors:	4		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/45/17/94 W LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	1236,98
-------------------	----------------














Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	---------------



Door F R, Bad repair, Paint	0,00
-----------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------

			Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
			Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
			Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20